

AlephObjects.com

3D Printers, Parts, and Plastics

+1-970-377-1111

shop@alephobjects.com

626 West 66th Street

Loveland, Colorado 80538



Service Bulletin


Affected product: LulzBot Single Extruder Tool Head v2

Effective date: June 3, 2015


Service issue: Some LulzBot Single Extruder Tool Head v2 may have an incorrect jumper wire included. The incorrect jumper contains: three pin output to three pin output. The correct jumper contains: two pin input to three pin output.

Indication:

Incorrect jumper (Output to Output):



Correct jumper (Input to Output):



Corrective Action:

Contact the Support Team by sending an email to Support@LulzBot.com with the following information:

- Shipping and Contact information
- Order number for LulzBot Single Extruder Tool Head v2 purchase

A replacement jumper will be sent at no cost to you. We apologize for any inconvenience this may have caused and appreciate your business.